TECHNICAL NOTICE

Please be advised of following modification on OREC machine(s).

MODEL	HRH801		
Issued Date	August 27, 2019		
Issued Number	HRH801-101-2		
New Number		Old Number	
0225-12600 0225-60400	Under Bonnet CMP Side Cover CMP	0225-12500 0225-60300	Under Bonnet CMP Side Cover CMP
Reason of Modification : To change the handle, the position of the handle, and other related parts in order to prevent the wire from melting.		Interchangeability : New –> Old (impossible) This modification covers following model(s) : HRH801	

(NEW)



0225-12600 Under Bonnet CMP



0225-60400 Side Cover CMP

(OLD)



0225-12500 Under Bonnet CMP



0225-60300 Side Cover CMP

Modification Starts from : HRH801 production start from December 2019

Remarks :

OREC Co., Ltd.
548-22, Hiyoshi, Hirokawa-Machi, Yame-Gun, Fukuoka, 834-0195, Japan
TEL : 0943-32-5057 FAX : 0943-32-3518