

TECHNICAL NOTICE


Please be advised of following modification on OREC machine(s).

MODEL	HRH801		
Issued Date	August 27, 2019		
Issued Number	HRH801-101-3		
New Number			Old Number
0225-73300	Knife Clutch Wire	0225-72200	Knife Clutch Wire
0225-73400	Driving Clutch Wire	0225-72300	Driving Clutch Wire
0225-73500	Change Wire	0225-72400	Change Wire
0225-73600	Handle Up/Down/Left/Right Wire	0324-72100	Handle Up/Down/Left/Right Wire
0334-70800	Side Clutch Wire	83-1614-962-10	Side Clutch Wire

Reason of Modification :
To change the handle, the position of the handle, and other related parts in order to prevent the wire from melting.

Interchangeability :
New -> Old (impossible)

This modification covers following model(s) :
HRH801



Modification Starts from : HRH801 production start from December 2019

Remarks :

OREC Co., Ltd.
548-22, Hiyoshi, Hirokawa-Machi, Yame-Gun, Fukuoka, 834-0195, Japan
TEL : 0943-32-5057 FAX : 0943-32-3518