

FIXING SCREWS OF THE TURBINE BLADES REF. 00.90.07.1060

The replacement of the turbine blades is a rather frequent maintenance operation. To simplify this operation, the fixing screws have been modified.

In the past the fixing screws were standard UNI.5932 setscrews, male spanner 8 mm. But were getting full of dirt and it was very difficult to insert the spanner.

The new screws are GF design with hexagonal full head, socket spanner 12mm with better grip and do not get full with dirt.

The new screw is interchangeable.

Relevant references:

01.90.07.1060 screw
01.90.00.2050 Turbogross turbine blades assy
01.90.00.2060 T1-2-4 turbine blades assy
remain unchanged

From the 16th of May onwards if you order these screws, you will get the new ones.

